ATTY DOCKET NO: 10559-561001 CLIENT DOCKET NO: P-12581

## ABSTRACT

An IQ imbalance error-correction method includes estimating, on the basis of a constellation error in a received OFDM signal, an extent of an I/Q imbalance error, caused by direct IQ conversion of the received OFDM signal. On the basis of that extent, an equalizing transformation that reduces that error is estimated.